

## Adhesive for screws

### Application Instructions:

1. Shake well before use.
2. Clean the screws and let them dry if necessary.
3. Apply a drop to the end of the thread.
4. Remove the excess.
5. Do not move the screws for at least 15 minutes after application.

Note: 40% resistance after 60 minutes.

Full effect after 24 hours

Do not use on plastics.

Operating temperature range from -50°C to +150°C.

6 ml pack.

Made in the EU

Importer: MEFO SPORT CENTRUM s.r.o.  
Jinín 60, Strakonice 38601, [www.mefo.cz](http://www.mefo.cz)