

Seats - Acerbis

Mounting: screw the saddle to the brackets on the motorcycle.

Inflate X-AIR saddles continuously to a maximum of 0.60 bar, do not over-inflate or drop. This will damage the saddle!

Maintenance: washable WAP, do not use aggressive chemicals.

ATTENTION! Do not test the elasticity or strength of the saddle with excessive force, the internal structure of the saddle may be damaged.

DO NOT BEND!

Dispose of the product environmentally at the end of its life.

THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY MISUSE OR IMPROPER INSTALLATION OF THIS PRODUCT

Made in ITALY

Imported by MEFO SPORT CENTRUM s.r.o.

Jinín 60, Strakonice 38601, www.mefo.cz