

- 1 Clean the surface from dirt and grease.
- 2 Apply Motoverde Rust Remover directly onto the rusted area using a brush.
- 3 Leave for 5–10 minutes.
- 4 Wipe away with a damp cloth or rinse thoroughly.
- 5 Repeat if necessary.
- 6 Small parts such as nuts and bolts can be submerged for 5–15 minutes.

Manufacturer: www.motoverde.com